

Inspection Photos

API: 071-07064

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/3/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07064 | Date: 8/3/2022

Inspection Photos



Photo 1. Facing south near the creek crossing along the main road. Noxious weeds are wilted and controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07064 | Date: 8/3/2022

Inspection Photos



Photo 2. Facing southwest at the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07064 | Date: 8/3/2022