

Inspection Photos

API: 071-07040

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/3/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07040 | Date: 8/3/2022

Inspection Photos



Photo 1. Facing west at the drainage crossing. This area has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07040 | Date: 8/3/2022

Inspection Photos



Photo 2. Further along the road there is erosion channeling occurring on the roadside. BMP's need to be installed to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07040 | Date: 8/3/2022

Inspection Photos



Photo 3. Stormwater should be directed off the road instead it appears to be going down the road causing erosion shown in previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07040 | Date: 8/3/2022

Inspection Photos



Photo 4. Facing west at the wellsite.

