

Inspection Photos

API: 071-07041

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/3/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07041 | Date: 8/3/2022

Inspection Photos



Photo 1. Facing west near the creek crossing along the main road. Noxious weeds are wilted and controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07041 | Date: 8/3/2022

Inspection Photos



Photo 2. Facing east at the creek crossing along the access road. Noxious weeds are wilted and controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07041 | Date: 8/3/2022

Inspection Photos



Photo 3. Facing northeast at the wellsite.

