

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2022

Submitted Date:

08/04/2022

Document Number:

688801192

FIELD INSPECTION FORM

Loc ID 453364 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100382
Name of Operator: CANFIELD DRILLING COMPANY
Address: BOX 453
City: FT MORGAN State: CO Zip: _____

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Chollett, Shannon		shannon.chollett@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453363	WELL	TA	12/15/2017	GW	077-10548	Canfield (OWP) 1	EI

General Comment:

On July 11, 2022 COGCC OWP Western Region EPS Jim Hughes conducted an environmental field inspection of the Canfield (OWP) #1. For the most recent field inspection report of this facility, please refer to document # 688801174. Water samples were collected from near the well head during this site visit. Samples were sent to Pace Analytical. The samples taken from near the well head were analyzed for Table 915-1 groundwater standards and Rule 615.e.2 constituents as part of REM #23846.

Inspected Facilities

Facility ID: 453363 Type: WELL API Number: 077-10548 Status: TA Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: Well _____ Comment: Canfield (OWP) #1 077-10548

Sample	Sample Type: PRODUCED			
Time: 07/11/2022 12:30 (MM/dd/yyyy hh:mm)	GPS: Lat 39.360250	Long -108.245890		
BTEX: YES	TPH: YES	Anion: YES	Captions: YES	General Chemistry: YES
Dissolved Methane: YES	Composition: _____	Stable Isotopes: _____	8260: YES	
8270: _____	RCRA Metals: _____	910-Metals: _____	PAH: _____	
Other: _____				
Comment: _____				

Lab:

Lab Name _____

Pace Analytical

COGCC Comments

Comment	User	Date
On July 11, 2022 COGCC OWP Western Region EPS Jim Hughes conducted an environmental field inspection of the Canfield (OWP) #1. For the most recent field inspection report of this facility, please refer to document # 688801174. Water samples were collected from near the well head during this site visit. Samples were sent to Pace Analytical. The samples taken from near the well head were analyzed for Table 915-1 groundwater standards and Rule 615.e.2 constituents as part of REM #23846.	hughesjo	08/04/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801193	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5821146