

Inspection Photos

API: 071-09287

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/3/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09287 | Date: 8/3/2022

Inspection Photos



Photo 1. Facing northwest the beginning of the access road. The road has not been recontoured and reclaimed. It does not appear the road is stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 8/3/2022

Inspection Photos



Photo 2. Facing northwest along the access road. There have been rock check dams installed however they are filled in with sediment and not properly installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 8/3/2022

Inspection Photos



Photo 3. Facing south along the access road. The road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 8/3/2022

Inspection Photos



Photo 4. There is a Russian olive tree growing on the side of the road. This is a list B noxious weed and need to be removed and controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 8/3/2022

Inspection Photos



Photo 5. Facing west toward the location. The location has not been recontoured. The location was reseeded and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 8/3/2022

Inspection Photos



Photo 6. Facing southeast at the location. The location was reseeded and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 8/3/2022

Inspection Photos



Photo 7. Facing east at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 8/3/2022

Inspection Photos



Photo 8. The electric utility remains at the southwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 8/3/2022

Inspection Photos



Photo 9. Facing west at the south fill slope side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 8/3/2022