

Inspection Photos

API: 071-09246

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/3/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022

Inspection Photos



Photo 1. Facing southwest the beginning of the access road. The road has not been recontoured and reclaimed. The roadside is not stabilized and there is signs or erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022

Inspection Photos



Photo 2. Facing southwest along the access road. There was recent work performed along the road. This area was partially excavated. Areas of disturbance need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022

Inspection Photos



Photo 3. Facing southwest along the access road. Excavated material was placed on the fill slope of the road. Areas of disturbance need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022

Inspection Photos



Photo 4. Facing southwest along the access road. There was recent work performed along the road. This area was partially excavated and material was placed on the road. Areas of disturbance need to be reclaimed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022

Inspection Photos



Photo 6. Facing southeast toward the access road and location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022

Inspection Photos



Photo 6. The electric utility remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022

Inspection Photos



Photo 7. Facing southeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022

Inspection Photos



Photo 8. Facing west at the location. There are areas of the location that have not established vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022

Inspection Photos



Photo 10. East side of the location facing southwest. There are areas of the location that have not established vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022

Inspection Photos



Photo 11. Facing west at the south side of the location. Vegetation is progressing in this area of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 8/3/2022