

Inspection Photos

Jul 27, 2022

Operator: North Shore Exploration and Production LLC - #10724

Location ID: 313188

Location Name: Martin Livestock-610N93W /17NWNW

Inspection Document #: 702800524

Moffat County, CO

NWNW Section 17 T10N R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Martin Livestock-610N93W /17NWNW
Location ID: 313188



Photo 1. Photo taken from the west of the Location shows the reclaimed access road. Perennial grass is well established, with occasional bare patches.



Photo 2. Photo taken from the west of the Location shows the reclaimed access road. Perennial grass is well established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800524

Inspection Photos

Location Name: Martin Livestock-610N93W /17NWNW

Location ID: 313188



Photo 3. Photo taken from the north of the Location shows vegetation establishment is not uniform. Bare patches are common.



Photo 4. Photo taken from the northeast shows an area where equipment was located which appears compacted, gravel remains and is bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800524

Inspection Photos

Location Name: Martin Livestock-610N93W /17NWNW

Location ID: 313188



Photo 5. Photo taken from the northeast shows an area where equipment was located which appears compacted, gravel remains and is bare of vegetation.



Photo 6. Photo taken from the south shows an area where vegetation establishment has largely failed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800524

Inspection Photos
Location Name: Martin Livestock-610N93W /17NWNW
Location ID: 313188



Photo 7. Photo taken to the northwest of the Location and 80 feet to the south of the Location access road shows a riser associated with the Location. The riser must be removed, and the area reclaimed.



Inspection Photos

Location Name: Martin Livestock-610N93W /17NWNW

Location ID: 313188



Photo 8. Photo taken from the northwest of the Location shows the reference area vegetation community is native rangeland.



Photo 9. Photo taken from the east of the Location shows the reference area vegetation community is native rangeland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800524