

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Speakman /A Pad

Location ID: 422301



Photo #7402 from entrance to location.



Photo #7403 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Speakman /A Pad

Location ID: 422301



Photo #7404 from entrance to location.



Photo #7405 Stained soils outside of containment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Speakman /A Pad

Location ID: 422301



Photo #7411 Unused equipment.

Photo #7413 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Speakman /A Pad

Location ID: 422301



Photo #7412 Oily fluids in containment.



Photo #7414 Oily fluids in containment.