

Caerus Piceance LLC  
B27  
Location # 335376



Location



location

Caerus Piceance LLC  
B27  
Location # 335376



Location



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Caerus Piceance LLC  
B27  
Location # 335376



**Erosion at pig station possibly coming from catch containment**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Caerus Piceance LLC  
B27  
Location # 335376



**Location**



**Debris**



Caerus Piceance LLC  
B27  
Location # 335376



**Valve missing cap/plug**



**Valve missing cap/plug**

