

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/04/2022

Submitted Date:

08/05/2022

Document Number:

701005557

**FIELD INSPECTION FORM**Loc ID 303591 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone          | Email                        | Comment |
|--------------|----------------|------------------------------|---------|
| Jones, Greg  | (970) 630-3909 | greg.jones@ownresources.com  |         |
| Dolezal, Pat | (970) 332-3585 | pat.dolezal@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 253330      | WELL | PR     | 11/02/1987  | GW         | 125-07207 | ROSE 2-18     | PR          |

**General Comment:**

Routine Inspection

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Two track through pasture |       |  |
| Corrective Action  |                           | Date: |  |

Overall Good: ☒

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | TANK LABELS/PLACARDS                                    |       |  |
| Comment:             | Metal sign by water tank                                |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | WELLHEAD  |       |  |
| Comment:             | Lease sign mounted to fence. Update to current operator |       |  |
| Corrective Action:   |   | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                                       |       |  |
|--------------------|---------------------------------------|-------|--|
| <b>Fencing/:</b>   |                                       |       |  |
| Type               | PUMP JACK                             |       |  |
| Comment:           | Metal panels around unit and wellhead |       |  |
| Corrective Action: |                                       | Date: |  |

|                           |                  |       |                 |
|---------------------------|------------------|-------|-----------------|
| <b>Equipment:</b>         |                  |       | corrective date |
| Type: Prime Mover         | # 1              |       |                 |
| Comment:                  | Arrow gas engine |       |                 |
| Corrective Action:        |                  | Date: |                 |
| Type: Pump Jack           | # 1              |       |                 |
| Comment:                  | Churchill unit   |       |                 |
| Corrective Action:        |                  | Date: |                 |
| Type: Ancillary equipment | # 1              |       |                 |
| Comment:                  | Gas scrubber     |       |                 |
| Corrective Action:        |                  | Date: |                 |
| Type: Deadman # & Marked  | # 1              |       |                 |
| Comment:                  |                  |       |                 |
| Corrective Action:        |                  | Date: |                 |

**Tanks and Berms:**

| Contents  | # | Capacity | Type           | Tank ID | SE GPS                |  |
|---|---|----------|----------------|---------|-----------------------|--|
| PRODUCED WATER  | 1 | OTHER    | PBV FIBERGLASS |         | 39.886520,-102.237410 |  |
| Comment: Fiberglass water tank 50% buried on north side of wellhead |   |          |                |         |                       |  |
| Corrective Action:  |   |          |                |         | Date:                 |  |

**Paint**

|                  |         |  |
|------------------|---------|--|
| Condition        |         |  |
| Other (Content)  |         |  |
| Other (Capacity) | 210bbls |  |
| Other (Type)     |         |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
|                    |          |                     |                     |             |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |   |       |      |             |           |         |    |               |    |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 253330  | Type: | WELL | API Number: | 125-07207 | Status: | PR | Insp. Status: | PR |
| Producing Well       |   |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production. Central meter run for (A. Welp 1, 44-13, Odell 2-7, Rose 2 -18) 3200' SW @ A. Welp #1 |       |      |             |           |         |    |               |    |
| Corrective Action:   |   |       |      |             |           |         |    | Date:         |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description    | URL   |
|--------------|----------------|---|
| 701005573    | location photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5822615">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5822615</a> |