

KP Kauffman Company INC, Champlin 321 Amoco A 1
005-06436

Inspection #688312788

7/20/2022

Routine Field Inspection



Colorado Oil and Gas Conservation Commission
39.71467, -104.40363, 5472.4ft, 324°
07/20/2022 02:11:38 PM



Colorado Oil and Gas Conservation Commission
39.71468, -104.40365, 5495.4ft, 288°
07/20/2022 02:11:53 PM



Colorado Oil and Gas Conservation Commission
39.71471, -104.40372, 5511.8ft, 295°
< 07/20/2022 02:13:05 PM



Unused
equipment, tank is
empty.

Colorado Oil and Gas Conservation Commission
39.71471, -104.40369, 5498.7ft, 258°
07/20/2022 02:12:13 PM



Tank battery from well.

Colorado Oil and Gas Conservation Commission
39.71469, -104.40366, 5498.7ft, 201°
07/20/2022 02:12:02 PM



Colorado Oil and Gas Conservation Commission
39.7138, -104.4037, 5488.8ft, 242°
07/20/2022 02:13:56 PM



Tank contents
and quantity
labels are worn.

Colorado Oil and Gas Conservation Commission
39.7138, -104.40369, 5492.1ft, 255°
07/20/2022 02:14:03 PM



Colorado Oil and Gas Conservation Commission
39.71356, -104.40374, 5446.2ft, 251°
07/20/2022 02:15:48 PM



Control weeds.

Colorado Oil and Gas Conservation Commission
39.71357, -104.40372, 5469.2ft, 241°
07/20/2022 02:15:56 PM



Colorado Oil and Gas Conservation Commission

39.71392, -104.40375, 5508.5ft, 348°

07/20/2022 02:16:42 PM



Colorado Oil and Gas Conservation Commission
39.71397, -104.4038, 5511.8ft, 52°
07/20/2022 02:16:58 PM



Andarko gas sales
line riser.

Colorado Oil and Gas Conservation Commission
39.71397, -104.40381, 5511.8ft, 2°
07/20/2022 02:17:05 PM



Cell phone telemetry.

Colorado Oil and Gas Conservation Commission
39.71381, -104.4037, 5502.0ft, 328°
07/20/2022 02:16:28 PM