

Inspection Photos

API: 055-06209

Operator: CAPTUREPOINT LLC

Inspection Date: 8/8/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06209 | Date: 8/8/2022

Inspection Photos



Photo 1. Facing south along the access road. There are noxious weeds along the road that need to be controlled. Red arrow → Scotch thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06209 | Date: 8/8/2022

Inspection Photos



Photo 2. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06209 | Date: 8/8/2022

Inspection Photos



Photo 3. Facing southwest at the north side of the location. There are noxious weeds along the north side of the location that need to be controlled.

Red arrow → Scotch thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06209 | Date: 8/8/2022