

Inspection Photos

API: 055-06301

Operator: CAPTUREPOINT LLC

Inspection Date: 8/8/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06301 | Date: 8/8/2022

Inspection Photos



Photo 1. Facing west at the entrance of the Gas Plant. There are noxious weeds along the road that need to be controlled. Red arrow → Diffuse knapweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 8/8/2022

Inspection Photos



Photo 2. Facing northwest at the Gas Plant. There are noxious weeds along the road that need to be controlled. Red arrow → Diffuse knapweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 8/8/2022

Inspection Photos



Photo 3. Facing southwest along the access road. There are noxious weeds that need to be controlled. Red arrow → Diffuse knapweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 8/8/2022

Inspection Photos



Photo 4. Facing northwest along the road. There is erosion along the road that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 8/8/2022

Inspection Photos



Photo 5. Facing southwest along the access road. There are noxious weeds that need to be controlled. Red arrow → Mullein.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 8/8/2022

Inspection Photos



Photo 6. Facing southwest along the road. There is erosion along the road that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 8/8/2022

Inspection Photos



Photo 7. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 8/8/2022

Inspection Photos



Photo 8. Facing toward the north side of the location. There are noxious weeds at the location that need to be controlled. Red arrow → Diffuse knapweed



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 8/8/2022