

Inspection Photos

API: 055-06142

Operator: CAPTUREPOINT LLC

Inspection Date: 8/8/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06142 | Date: 8/8/2022

Inspection Photos




Photo 1. Facing north along the access road. There are noxious weeds along the road that need to be controlled. Red arrow → Scotch thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 8/8/2022

Inspection Photos



Photo 2. Facing northeast toward the multi well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 8/8/2022

Inspection Photos




Photo 3. Facing southwest at the north side of the location. There are noxious weeds along the north side of the location that need to be controlled.

Red arrow → Musk thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 8/8/2022