

Inspection Photos

API: 055-06214

Operator: PETROGLYPH OPERATING CO

Inspection Date: 8/8/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/8/2022

Inspection Photos



Photo 1. Facing north toward the location. The pile of rock still remains at the southeast side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/8/2022

Inspection Photos



Photo 2. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/8/2022

Inspection Photos



Photo 3. There is a black pipe sticking out of the fill slope at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/8/2022

Inspection Photos



Photo 4. Facing southeast at the location. Perennial vegetation is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/8/2022