

# Inspection Photos

August 8, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 335045

Location Name: South Leverich /13-09 Pad

Inspection Document #: 702800550

Garfield County, CO

NESE Section 13 T7S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: South Leverich /13-09 Pad  
Location ID: 335045



**Photo 1.** Photo taken from the Location entrance at the northeast shows an overview of the of the southern portion of the production area.



**Photo 2.** Photo taken from the Location entrance at the northeast shows an overview of the northern portion of the production area. Photo also shows the gravel has been applied to the working pad area to address previous stormwater corrective actions.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800550



Inspection Photos  
Location Name: South Leverich /13-09 Pad  
Location ID: 335045



**Photo 3.** Photos show stained soils at the northeast of the Location which appear to be associated with the water truck.



Inspection Photos  
Location Name: South Leverich /13-09 Pad  
Location ID: 335045



**Photo 4.** Photo shows an example of scentless chamomile, a CO List B Noxious Weed found occasionally throughout the Location.



**Photo 5.** Photo shows an example of plumeless thistle. A CO List B Noxious Weed found occasionally throughout the Location.