

Loomis Photographs
Inspection Doc # 696304288
Loc ID 438327
API No. 123-39927





Debris, weeds, stained soil and unused tubing removed.