

Inspection Photos

August 8, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335049

Location Name: South Leverich 18-13 Pad

Inspection Document #: 702800557

Garfield County, CO

SWSW Section 18 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Location ID: 335049



to address previous stormwater corrective actions.

Inspection Photos
Location Name: South Leverich 18-13 Pad
Location ID: 335049



Photo 2. Photo taken from the south of the Location shows storage of unused equipment. Form 4, request to store equipment is “In Process”.



Photo 3. Photo shows methanol tank has been labeled, addressing a previous corrective action.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800557

Inspection Photos
Location Name: South Leverich 18-13 Pad
Location ID: 335049



Photo 4. Photo taken from the south of the Location shows an example of bull thistle, (CO List B Noxious Weed) found throughout the Location.



Photo 5. Photo taken from the east of the Location shows an example of plumeless thistle, (CO List B Noxious Weed) found throughout the Location.

Inspection Photos
Location Name: South Leverich 18-13 Pad
Location ID: 335049



Photo 6. Photo taken from the east of the Location shows plumeless and bull thistle rosettes. Inset taken to the north shows plumeless thistle.



Photo 7. Photo taken from the east of the Location shows multiple noxious thistles which appear to have been recently treated. Many noxious weeds remain untreated. See Photos 4, 5, 6.