

Inspection Photos

August 8, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335121

Location Name: Mead /30-12 Pad

Inspection Document #: 702800561

Garfield County, CO

NWSW Section 30 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mead /30-12 Pad
Location ID: 335121



Photo 1. Photo taken from the Location entrance to the north shows an overview of the production area.



Photo 2. Photo taken from the Location entrance to the north shows an overview of the production area.

Inspection Photos
Location Name: Mead /30-12 Pad
Location ID: 335121



Photo 3. Photo taken from the northeastern production area shows an anchor marker in disrepair.



Photo 4. Photo taken from the southeastern production area shows an unmarked anchor.

Inspection Photos
Location Name: Mead /30-12 Pad
Location ID: 335121



Photo 5. Photo taken from the southeast of the Location at the top of the cut slope shows Scotch thistle, a CO List B Noxious Weed. Two plants were observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800561

Inspection Photos
Location Name: Mead /30-12 Pad
Location ID: 335121



Photo 6. Photo taken from the west of the Location shows the vegetation in the interim area is dominated by rubber rabbitbrush. Crested wheatgrass and smooth brome (introduced perennial grasses) are also present.



Photo 7. Refer to Photo 6 comment.