

# Inspection Photos

API: 061-06608

Operator: OKT RESOURCES LLC

Inspection Date: 8/10/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06608 - Date: 8/10/2022

## Inspection Photos



**Photo 1.** Facing southwest toward the location. The location consists of undesirable weed and sparse desirable vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06608 - Date: 8/10/2022

## Inspection Photos



**Photo 2.** Facing north at the location. The location consists of undesirable weed and sparse desirable vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06608 - Date: 8/10/2022

## Inspection Photos



**Photo 3.** The gas meter run remains at the south side of the location. All equipment should have been removed within 3 months of well abandonment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06608 - Date: 8/10/2022

## Inspection Photos



**Photo 4.** The gas meter run remains at the south side of the location. All equipment should have been removed within 3 months of well abandonment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06608 - Date: 8/10/2022