

Inspection Photos

Location Name: Extraction Windsor Land Application Site

Facility ID: 449314, Remediation Project 15605



Photo 1 West end of land application area looking north



Photo 2 West End of land application area looking northeast



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Extraction Windsor Land Application Site

Facility ID: 449314, Remediation Project 15605



Photo 3 Center-west end of land application area looking north



Photo 4 Center-west end of land application area looking east



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Extraction Windsor Land Application Site

Facility ID: 449314, Remediation Project 15605



Photo 5 Center east end of land application area looking northwest



Photo 6 Center east end of land application area looking north



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Extraction Windsor Land Application Site

Facility ID: 449314, Remediation Project 15605



Photo 7 Center east end of land application area looking northeast



Photo 8 East end of land application area looking north, viewing ground example of vegetative growth



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources