

Inspection Photos

Location Name: David Howard #B1 well and Facility 7 Battery

Location ID: 317802



Photo 1 HOZ sep fire damage



Photo 2 HOZ sep fire damage



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: David Howard #B1 well and Facility 7 Battery

Location ID: 317802



Photo 3 HOZ sep fire damage



Photo 4 Vert sep and ECD

Inspection Photos

Location Name: David Howard #B1 well and Facility 7 Battery

Location ID: 317802



Photo 5 Cement vault not placards or tank volume markings



Photo 6 TNK BTRY



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: David Howard #B1 well and Facility 7 Battery

Location ID: 317802



Colorado Oil and Gas Conservation Commission

Photo 7 loc pic



Colorado Oil and Gas Conservation Commission

Photo 8 tnk btry sign

Inspection Photos

Location Name: David Howard #B1 well and Facility 7 Battery

Location ID: 317802



Photo 9 well head



Photo 10 PU

Inspection Photos

Location Name: David Howard #B1 well and Facility 7 Battery

Location ID: 317802




Photo 11 recirc pump. Stained soil around pump. And mechanical issue.



Photo 12 Recirc pump house.