

# Inspection Photos

API: 061-06590

Operator: OXY USA INC

Inspection Date: 8/11/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06590 | Date: 8/11/2022

## Inspection Photos



**Photo 1.** Facing southeast along the former access road. Vegetation has not re-established in this area and there is erosion. Location is shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06590 | Date: 8/11/2022

## Inspection Photos



**Photo 2.** Facing southeast at the location. The fill slope has not been recontoured. There is no vegetation growth along this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06590 | Date: 8/11/2022

## Inspection Photos



**Photo 3.** Facing southwest at the location. There is no vegetation observed in this bare area approximately 120'x120'. There may be soil issues preventing vegetation establishment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06590 | Date: 8/11/2022

## Inspection Photos



**Photo 4.** Facing southwest along the cut slope which is not recontoured. There are signs of erosion and soils are not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06590 | Date: 8/11/2022

## Inspection Photos



**Photo 5.** Facing southwest at the at the eastern corner of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06590 | Date: 8/11/2022

## Inspection Photos



**Photo 6.** Facing east toward the surrounding undisturbed rangeland consisting of Blue grama, Sand dropseed among other native species.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06590 | Date: 8/11/2022

## Inspection Photos



**Photo 7.** Drone aerial photo facing southeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06590 | Date: 8/11/2022

## Inspection Photos



**Photo 8.** Drone aerial photo facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06590 | Date: 8/11/2022