




## WELLHEAD ABANDONMENT FORM

<b>SITE NAME:</b> UPRR Pan Am B1 41							<b>DATE:</b> 5/18/2022	<b>REM. PROJECT #:</b>	<b>WEATHER:</b> Sunny, 80 F
<b>SITE DIRECTIONS:</b> Cr 40 & Cr 15, E 0.1, N 0.1 into							<b>CLIENT:</b> Oxy		
<b>LEGALS AND LAT/LONG:</b> 40.278246, -104.920823							<b>TASMAN PERSONNEL:</b> Patrick Downs		
<b>SOIL TYPES:</b> Clayey Sand - SC							<b>SURFACE GRADIENT:</b> Northwest		
<b>SOIL SAMPLING</b>							<b>FACILITY INFRASTRUCTURE</b>		
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT	Quantity	
							Above Ground Storage Tank (AST)		
5/18/2022 13:00	WH-B01@6'	19.7	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel		
5/18/2022 13:02	WH-N01@5'	15.9	No Staining	No Odor	Yes	N/A	Separator		
5/18/2022 13:04	WH-S01@5'	2.7	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)		
5/18/2022 13:06	WH-E01@5'	0.6	No Staining	No Odor	Yes	N/A	Dump Line		
5/18/2022 13:08	WH-W01@5'	0.2	No Staining	No Odor	Yes	N/A	Wellhead	1	
5/18/2022 13:10	WHS-N01@3"	9.2	No Staining	No Odor	Yes	N/A	Flowline		
5/18/2022 13:12	WHS-S01@3"	1.3	No Staining	No Odor	Yes	N/A	Other:		
5/18/2022 13:14	WHS-E01@3"	0.1	No Staining	No Odor	Yes	N/A	Soil Loads Removed		
5/18/2022 13:16	WHS-W01@3"	0.2	No Staining	No Odor	Yes	N/A	<b>IMPACTED SOIL IDENTIFIED?</b>		
							<b>ESTIMATED VOLUME OF IMPACTS:</b>		
							Date	Number	CY
							Total Removed	0	0
							<b>Disposal Facility:</b>		
							Groundwater Recovery		
							<b>DATE GW ENCOUNTERED:</b>		<b>DEPTH:</b>
							<b>GROUNDWATER IN CONTACT WITH IMPACTED SOIL?</b>		
							<b>LNAPL OR SHEEN OBSERVED ON GW?</b>		
<b>GROUNDWATER SAMPLING</b>							Date	BBLs	
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?			
							Total Removed	0	
							<b>Disposal Facility:</b>		



<b>Equipment ID:</b>		<b>Equipment Type:</b>		<b>Equipment ID:</b>		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>		<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b>				<b>Notes/Conditions:</b>			

**Photographic Log**

									
						<b>Equipment ID:</b>		<b>Equipment Type:</b>	
						<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
						<b>Notes/Conditions:</b>			