



00334162

## WELL SITE INSPECTION FORM

LOCATION NESW 21-35-60WFIELD W/COPERATOR HUCKABAY LTDCOUNTY ADAMSWELL NAME LINNEBUR 1-21PERMIT # 86-351

## DATE OF INSPECTION DURING DRILLING: \_\_\_\_\_

RIG \_\_\_\_\_

SURFACE CASING: \_\_\_\_\_

DEPTH: \_\_\_\_\_

BOP'S \_\_\_\_\_

RETURNS: \_\_\_\_\_

WOC: \_\_\_\_\_

CONTACT \_\_\_\_\_

CMT VOL: \_\_\_\_\_

ADEQUATE AQUIFER PROTECTION? \_\_\_\_\_

COMMENTS \_\_\_\_\_

## DATE OF INSPECTION AFTER COMPLETION: \_\_\_\_\_

FRACED: YES \_\_\_ NO \_\_\_

PRODUCTION STRING: \_\_\_\_\_

WATER DISPOSAL: PITS \_\_\_, INJECTED \_\_\_, COMMERCIAL \_\_\_, UNKNOWN \_\_\_, N.A. \_\_\_

PITS: PERMIT Y \_\_\_ N \_\_\_, SKIM TANK Y \_\_\_ N \_\_\_, DIMENSIONS \_\_\_\_\_

LEASE SIGN: YES \_\_\_ NO \_\_\_ TANK ID: YES \_\_\_ NO \_\_\_ NA \_\_\_ FENCED: YES \_\_\_ NO \_\_\_

SURFACE EQUIPMENT: \_\_\_\_\_

COMMENTS: \_\_\_\_\_

DATE OF P&A INSPECTION 9/19/86PITS BACKFILLED: YES ☒ NO ☒SURFACE RECLAIMED: YES ☒ NO \_\_\_HOLE MARKER: YES \_\_\_ NO ☒SITE CLEAN: YES ☒ NO \_\_\_BOND RELEASE OK: YES ☒ NO \_\_\_

LANDOWNER RELEASE: YES \_\_\_ NO \_\_\_

COMMENTS: GOOD RESTORATION - PREVIOUS INSPECTOR SHOWED PITS NOT BACKFILLED

## DATE OF SAFETY INSPECTION \_\_\_\_\_

COMMENTS: \_\_\_\_\_

INSPECTOR SSKAPI No. 05-001-08778P&A Inspected: Yes ☒ No \_\_\_