



N

API # 05-001-08778

LEASE INSPECTION FORM

Date 6/26/86
Operator HUCKABAY Field W/C
Lease Name & No. LINNEBUR 1-21 County ADAMS
Tank Battery No. _____ Location NESW 21-35-60W
Legal Description
Type of Inspection P+A
Water Inflow _____ (Bbls. Per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)
Type of Tank

SKIM TANK _____

Pit No. 1 HOLE APPARENTLY P+A OK - NO SURFACE

Pit No. 2 RESTORATION - ALL PITS STILL PRESENT

Pit No. 3 _____

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

RECOMMENDED ACTION (If Required) File

INSPECTOR JSK