

Inspection Photos
Location Name: MILLER-66N64W /29SESE
Location #: 323297



Photo #1
Miller 16-29 (05-123-12830) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 10 yds.



Photo #2
Miller 16-29 Battery site
Abandoned: ALL Equipment Removed