

Final Reclamation Inspection

August 4, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336094

Inspection Document #: 697504104

Weld County, CO

SENE Section 33 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPV-63N66W /33SENE
Location ID: 336094



Photo 1. Photo taken last year (5/18/2021) from the associated offsite tank battery location, facing West. Photo illustrates the tank battery appears reflective of reference areas.

Inspection Photos
Location Name: UPV-63N66W /33SENE
Location ID: 336094



Photo 2. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates the tank battery area is not in crop production at this time but crop growth was observed last year with no issues.



Inspection Photos
Location Name: UPV-63N66W /33SENE
Location ID: 336094



Photo 3. Photo taken south of the well location, facing North. Photo illustrates the access road and well location are reflective of reference crop areas.

