

Final Reclamation Inspection

August 4, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 327358

Inspection Document #: 697504106

Weld County, CO

NWNE Section 33 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: SARCHET UPRR-63N66W /33NWNE

Location ID: 327358



Photo 1. Photo taken last year (5/18/21) from the associated offsite tank battery location, facing South. Photo illustrates the tank battery appears reflective of reference areas.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504106

Inspection Photos

Location Name: SARCHET UPRR-63N66W /33NWNE

Location ID: 327358



Photo 2. Photo taken last year (5/18/21) from the associated offsite tank battery location, facing East. See comments under Photo 1.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504106

Inspection Photos
Location Name: SARCHET UPRR-63N66W /33NWNE
Location ID: 327358



Photo 3. Photo taken last year (5/18/21) from the associated offsite tank battery location, facing North. Photo illustrates active midstream equipment, which appears to be associated with nearby active locations.

Inspection Photos

Location Name: SARCHET UPRR-63N66W /33NWNE

Location ID: 327358



Photo 4. Photo taken from the western well location access road, facing East. Photo illustrates the access road and well location are reflective of reference crop areas.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504106