



99999999

WELL SITE INSPECTION FORM

WELL NAME Kiader 1
OPERATOR Hawks
LOCATION NESW 18-3560W
FIELD Flint

API NUMBER 05 - 001 - 5042
PERMIT NUMBER _____
COUNTY Adams
INSPECTOR Bentley

AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) _____ DATE 10-13-88 FN _____ FD _____ WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: 2-9-61 DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES ☒ NO _____ PITS BACKFILLED: YES ☒ NO _____
MATERIAL BURIED: YES ☒ NO _____ NA _____ SITE CLEAN: YES ☒ NO _____
BOND RELEASE OK: YES _____ NO ☒ FED _____ HOLE MARKER: YES _____ NO ☒

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS plowed (cut wheat) 4 water wells in area

New house now again abandoned



00334124