

Inspection Photos and Issue Report

8/17/2022

Operator: CAERUS PICEANCE LLC #10456

Location #479214

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #479214



Photo 1: Tanks/Battery on the north end of the Location; tanks missing required labeling.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #479214



Photo 2: Photos taken from the perimeter topsoil stockpile on the east end of the Location. Photos examples showing topsoil remains (red arrow) in use as part of the Location perimeter stormwater ditch/berm and sediment trap (yellow arrow). Photos also examples showing BMPs to protect and stabilize the topsoil stockpiles remains missing or insufficient; hydromulch previously implemented has not been maintained in proper functioning condition.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #479214



Photo 3: Photos examples showing BMPs to protect the topsoil stockpiles are missing or insufficient; soils at the stockpiles are exposed and at risk to wind and water erosion. Arrow shows areas of hydromulch that had been previously applied; BMP has not been maintained.




Photo 4: Top photos show areas identified in the 9/3/2021 and 6/22/2022 inspections, where offsite sediment transport from the topsoil stockpiles is evident. Bottom photos from 8/17/2022 show BMPs to protect/stabilize topsoil stockpiles, and to prevent offsite sediment (red arrow) transport remains inadequate and/or have not been maintained.