

Inspection Photos
Location Name: Weld-Weitzel 5-33
Location ID: 317747



Photo 1 – Pumping Unit



Photo 2 – Well Sign

Inspection Photos
Location Name: Weld-Weitzel 5-33
Location ID: 317747



Photo 3 – Wellhead



Photo 4 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Weld-Weitzel 5-33
Location ID: 317747



Photo 5 – Heater Treater



Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Weld-Weitzel 5-33
Location ID: 317747



Photo 7 – Tank Battery



Photo 8 – Tank Battery

Inspection Photos
Location Name: Weld-Weitzel 5-33
Location ID: 317747



Photo 9 – Tank Battery



Photo 10 – Tank Battery