

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KRK-67S92W /7SESW

Location ID: 324006



Photo #7508 from entrance to location.



Photo #7510 from entrance to location.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC KRK-67S92W /7SESW

Location ID: 324006



**Photo #7507** Multiple places with undesirable plant species.



**Photo #7511** Multiple places with undesirable plant species.



## Inspection Photos

**Location Name: CAERUS PICEANCE LLC KRK-67S92W /7SESW**

**Location ID: 324006**



**Photo #7513 Multiple places with undesirable plant species.**