

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 3 Pump Jack.

Photo 4 ancillary equip.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 5 TB sign.

Photo 6 TB.



Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 7 HHS, pump and flow line manifold.

Photo 8 Gas Meter Run, card indicates current calibration.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 9 Stained Soil by NE crude tank, pinhole leak.