

Inspection Photos

API: 071-09918

Operator: BNL (ENTERPRISE) INC

Inspection Date: 8/23/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 1. Facing north along the access road. There are signs of erosion along the road that need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 2. Facing west along the access road. There are signs stormwater is pooling along the road. The road will need to be stabilized with BMP's



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 3. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 4. Facing southwest toward the fill slope of the well pad. There is erosion occurring along the fill slope. The fill slope needs to be recontoured and stabilized for interim reclamation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 5. Facing northwest at the southeast corner of the location. Stormwater is being concentrated to this area. The silt fence is not adequate and additional BMP's need to be installed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 6. Stormwater is flowing underneath the silt fence in the southeast corner of the location. The silt fence is not adequate and additional BMP's need to be installed in this area. Silt fence is only a temporary erosion control and long term erosion controls need to be installed e.g. sediment trap, rock rip/rap, seeding, vegetation, ect.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 7. Facing northwest toward the location. The well pad location needs to be recontoured and reclaimed per 1003 Rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 8. Facing southwest toward the topsoil pile. It does not appear the entire topsoil pile was seeded as vegetation is not establishing. All unused disturbed areas will need to be reclaimed and part of the topsoil will need to be replaced.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 9. Facing northeast toward the location. The well pad location needs to be recontoured and reclaimed per 1003 Rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 10. Southwest side of the location facing northwest. There are wattles installed along the perimeter swale. The disturbed soils will need to be reclaimed for long term stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 11. Northwest side of the location facing southwest toward the cut slope. The cut slope needs to be stabilized with interim reclamation. All unused equipment needs to be removed. Drill pipe, wood ties, ect.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 12. The drilling pipe needs to be remove per rule 606.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022

Inspection Photos



Photo 13. Facing northwest toward the location. The open top tank was removed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 8/23/2022