

Final Reclamation Inspection

June 23rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323171

Inspection Document #: 701900431

NWNW Section 24 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Nadine 1-24
Location ID: 323171



Photo 1. 2021 aerial imagery of the well pad and tank battery. Note: well pad falls within a commercial lot owned by Western Equipment Truck Inc.

Inspection Photos
Location Name: Nadine 1-24
Location ID:323171



Photo 2. Overview photo of the well pad taken at ground level from the western edge facing east. The well location falls within a developed area and looks similar to the surrounding area.

Inspection Photos
Location Name: Nadine 1-24
Location ID:323171



Photo 3. Overview photo of the tank battery taken at ground level from the western edge facing east.

Inspection Photos
Location Name: Nadine 1-24
Location ID:323171



Photo 4. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Nadine 1-24
Location ID:323171



Photo 5. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing east. Note: tank battery shows limited desirable species and is dominated by kochia.