

# Final Reclamation Inspection

June 23rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 328363

Inspection Document #: 701900432

SWSW Section 21 T5N R64W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Elder 13-21  
Location ID: 328363



**Photo 1.** 2019 aerial imagery of the well pad and tank battery. Note: disturbance falls within the Rangeview Ranches subdivision.

Inspection Photos  
Location Name: Elder 13-21  
Location ID:328363



**Photo 2.** Overview photo of the well pad taken at ground level from the southern edge facing north.



Inspection Photos  
Location Name: Elder 13-21  
Location ID:328363



**Photo 3.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Elder 13-21  
Location ID:328363



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing east. Note: russian thistle seedlings observed dominating well pad and tank battery disturbance indicated by white arrow.



Inspection Photos  
Location Name: Elder 13-21  
Location ID:328363



**Photo 5.** Overview photo of the tank battery taken at ground level from the eastern edge facing west.



Inspection Photos  
Location Name: Elder 13-21  
Location ID:328363



**Photo 6.** Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Elder 13-21  
Location ID:328363



**Photo 7.** Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: russian thistle seedlings observed dominating well pad and tank battery disturbance indicated by white arrow.