

Final Reclamation Inspection

June 29th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 306121

Inspection Document #: 701900446

SENE Section 26 T7N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cecil 42-26
Location ID: 306121




Photo 1. 2020 aerial imagery of the well pad, tank battery and tank battery reference area. Note: well pad and tank battery now reside in the Cecil Dairy facility.

Inspection Photos
Location Name: Cecil 42-26
Location ID:306121



Photo 2. Overview photo of the well pad taken at ground level from the eastern edge looking west.

Inspection Photos
Location Name: Cecil 42-26
Location ID:306121



Photo 3. Overview photo of the tank battery taken at ground level from the eastern edge looking southwest. Note: tank battery is scheduled for 2022 maintenance. Tank battery will remain with a no status until it can be re-inspected in 2023.