



**Inspected Facilities**

Facility ID: 281240 Type: WELL API Number: 123-23373 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/23/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 35 Fluid Type: None

End Surf Csg Pressure: --

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Follow up inspection to Doc# 702400630 in response to FIRR #403096861. Based on Photos submitted by operator corrective actions are complete. (Photos attached to FIRR)	revasr	08/24/2022