



**Inspected Facilities**

Facility ID: 281232 Type: WELL API Number: 123-23359 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/23/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Follow up inspection to Doc# 702400641 in response to FIRR #403096865. Based on Photos submitted be operator corrective actions are complete. (Photos attached to FIRR)	revasr	08/24/2022