


Inspection Photos


Location Name: Pine River Unit 3-31 1
Location ID: 325488



IMG 01
Well sign



IMG 02
Location overview



IMG 03
Liner



IMG 04
Chemical storage



IMG 05
Material handling



IMG 06
Material handling



IMG 07
Vehicle parked off road



IMG 08
Trash on access road



IMG 09
Sediment stockpiled



IMG 10
Culvert inlet



IMG 11

Erosion in drainage ditch

IMG 12