



Inspection Photos  
Location Name: Oran W Short A 2  
Location ID: 326647



IMG 01  
Well sign



IMG 02  
Location overview



**IMG 03**  
**Lube oil**

**IMG 04**