

Inspection Photos

August 23, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334942

Location Name: Craig-66S93W /35NESW

Inspection Document #: 702800576

Garfield County, CO

NESW Section 35 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Craig-66S93W /35NESW
Location ID: 334942



Photo 1. Photo taken from the north shows an overview of the eastern production area.



Photo 2. Photo taken from the north shows an overview of the western production area.

Inspection Photos
Location Name: Craig-66S93W /35NESW
Location ID: 334942



Photo 3. Photo taken from the northwest shows signage has been installed at the tank battery to address a previous corrective action.



Photo 4. Photo shows a close-up of battery signage.

Inspection Photos
Location Name: Craig-66S93W /35NESW
Location ID: 334942



Photo 5. Photo taken from the south shows the western interim area is well vegetated with perennial grasses.



Photo 6. Photo taken from the south shows the southern interim area and fill slope are well vegetated with perennial grasses.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800576