

UPRC 9-11K

Photographic Log

Remediation #22956


Wellhead and Flowline Decommissioning



EAGLE
ENVIRONMENTAL
CONSULTING, INC.

8000 W 44th Ave, Wheat Ridge, CO 80033
Ph: 303-433-0479 • F: 303-325-5449

Wellhead



Wellhead sample locations looking north.
SVP = soil vapor point



Wellhead surface sample locations looking northwest.

Wellhead



Wellhead surface sample locations looking southeast.
SVP = soil vapor point



Wellhead background sample location looking north.

Wellhead



Wellhead background sample location looking southeast



Wellhead background sample location looking northwest.

Flowline



Flowline soil screening location looking south.



Flowline soil screening location looking south.

Flowline



Flowline soil screening location looking south.



Flowline soil sampling location looking south.