

Inspection Photos

API: 071-09331

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 8/25/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09331 | Date: 8/25/2022

Inspection Photos



Photo 1. Facing west toward the location. There has been topsoil spread over this area and vegetation is beginning to germinate.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09331 | Date: 8/25/2022

Inspection Photos



Photo 2. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09331 | Date: 8/25/2022