

Inspection Photos

API: 071-09344

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 8/25/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/25/2022

Inspection Photos



Photo 1. Facing southeast along the pre-existing access road. There are water bars installed along the road however, this area stormwater is overtopping the water bar.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/25/2022

Inspection Photos



Photo 2. Facing southeast along the pre-existing access road. This area has been reseeded and vegetation is germinating.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/25/2022

Inspection Photos



Photo 3. Facing southwest toward the location. The area of previous erosion has mostly been filled in and reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/25/2022

Inspection Photos



Photo 4. There is still part of the erosion channel that needs to be repaired and stabilized at the north portion of the location.



Photo 5. There is still part of the erosion channel that needs to be repaired and stabilized at the southeast portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/25/2022

Inspection Photos



Photo 5. Facing southwest at the location. This area has been regraded and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/25/2022