

# Inspection Photos

API: 071-08575

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 8/25/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/25/2022

## Inspection Photos



**Photo 1.** Facing south toward the location. This area at the north side of the location has been reclaimed with topsoil spread over this area. Vegetation was beginning to germinate in this reclaimed area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/25/2022

## Inspection Photos



**Photo 2.** Center of the location facing south. The perennial vegetation is progressing throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/25/2022

## Inspection Photos



**Photo 3.** Center of the location facing south. The perennial vegetation is progressing throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/25/2022

## Inspection Photos



**Photo 4.** Facing southeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/25/2022

## Inspection Photos



**Photo 5.** Facing north at the west side of the location. The area shown at red arrow where erosion was occurring has been reclaimed with topsoil spread over the area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/25/2022

## Inspection Photos



**Photo 6.** Facing southeast at the area where topsoil was spread to facilitate vegetation establishment. Vegetation was beginning to germinate in this reclaimed area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/25/2022