

Inspection Photos and Issue Report

8/17/2022

Operator: CAERUS PICEANCE LLC #10456

Location #479185

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #479185



Photo 1: Photo shows signage associated with the ELU O13-496 Pad remains missing from Location entrance. Permit information not posted in a protected and conspicuous place on location.