

Inspection Photos

Location Name: MUSTANG RESOURCES LLC YOUNBERG-66S94W /23SESW

Location ID: 323785



Photo #7561 from entrance to location.



Photo #7562 from entrance to location.

Inspection Photos

Location Name: MUSTANG RESOURCES LLC YOUNBERG-66S94W /23SESW

Location ID: 323785



Photo #7563 from entrance to location.



Photo #7564 Unregistered domestic tap.

Inspection Photos

Location Name: MUSTANG RESOURCES LLC YOUNBERG-66S94W /23SESW

Location ID: 323785



Photo #7564 Unregistered domestic tap.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources