

# Inspection Photos

August 23, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334934

Location Name: Shaeffer-67S93W /1SESW

Inspection Document #: 702800579

Garfield County, CO

SESW Section 1 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
 Location Name: Shaeffer-67S93W /1SESW  
 Location ID: 334934



**Photo 1.** Photo taken from the north of the Location shows signage has been installed at the tank battery to address a previous corrective action.



**Photo 2.** Refer to Photo 1 comment.



**COLORADO**  
 Oil & Gas Conservation  
 Commission

Department of Natural Resources

Inspection Number: 702800579

Inspection Photos  
Location Name: Shaeffer-67S93W /1SESW  
Location ID: 334934



**Photo 3.** Photo shows the production area.



**Photo 4.** Photo shows the production area



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800579